



order	description
<b>F5P</b>	switch, 25 amp
<b>PX5</b>	brass male coupler
<b>PX29G</b>	gasket
<b>SR37</b>	strain relief, metal
<b>SW101</b>	main housing
<b>SW102</b>	stainless steel under carriage
<b>SW107</b>	solenoid bracket
<b>SW109</b>	stainless steel vacuum pick-up tool
<b>SW116</b>	clamp, motor
<b>SW117</b>	bearing plate lh
<b>SW118</b>	bearing plate rh
<b>SW119</b>	manifold, spray tip
<b>SW122</b>	pigtail, electrical
<b>SW123</b>	cogged timing belt, for brush
<b>SW124</b>	small pulley
<b>SW126</b>	shaft, brush
<b>SW125</b>	large pulley
<b>SW128</b>	bearing housing
<b>SW129</b>	bronze bearing (2 required)
<b>SW130</b>	permanent magnet motor
<b>SW132</b>	solenoid, mopd, 250 psi (peb)
<b>SW132-4</b>	solenoid, mopd, 400 psi (peb-tm)
<b>SW132W</b>	solenoid, o-ring
<b>SW133A</b>	brass spray nozzle
<b>SW134</b>	spray nozzle .015 1/8" npt stainless steel (peb-tm)
<b>SW139</b>	1/8" street elbow
<b>SW142</b>	nylon cylindrical brush w/ solid pvc core
<b>SW143</b>	belt guard
<b>SW144</b>	hose ring assembly
<b>SW145</b>	2 amp circuit breaker
<b>SW146</b>	1/8" 45° street elbow
<b>SW147</b>	1/4" bushing
<b>SW148</b>	1/8" x 3" nipple
<b>SW149</b>	1/8" x 1/2" nipple
<b>SW150</b>	female receptacle (mates w/ SW151)
<b>SW151</b>	male rubber plug w/ build in strain relief
<b>SW154</b>	gasket solution/housing
<b>SW1520</b>	solenoid switch
<b>X8001</b>	top handle housing
<b>X8002</b>	bottom handle housing
<b>X80003</b>	switch lever
<b>X8005</b>	handle tube
<b>X8006</b>	switch bracket
<b>X8007</b>	handle grip
<b>X8009</b>	4" jumper wire
<b>X8010</b>	switch spring

order	description
<b>X8011B</b>	handle, tube 1-1/2" w/ bushings
<b>X8012</b>	handle clamp collar
<b>X8012A</b>	handle clamp assembly
<b>X8016</b>	knob
<b>X8018</b>	pivot shaft
<b>X8020</b>	washer axle
<b>X8022C</b>	2 wire cord assembly
<b>X8022D</b>	3 wire cord assembly
<b>X8025</b>	4" wheel
<b>X8026</b>	dowell pin
<b>X8027L</b>	left brace
<b>X8027R</b>	right brace
<b>X8028</b>	square, washer
<b>X8029</b>	axle
<b>X8034</b>	35 amp rectifier
<b>X8061</b>	clip switch lever
<b>X8100</b>	counter nut
<b>X8101</b>	spring, asher
<b>X8201</b>	8/32" x 3/8" type b screw
<b>X8202</b>	screw for SW117
<b>X8206</b>	10/32 screw for SW117
<b>X8208</b>	10-24 x 5/8" phillips head machine screw
<b>X8210</b>	wheel screw
<b>X8210-1</b>	short, switch housing screw and nut
<b>X8220</b>	long, switch housin screw
<b>X8225</b>	3/16" cut washer
<b>X8228</b>	spacer
<b>X8242</b>	hex nut
<b>X8246</b>	5/16 2-1/2" slotted screw
<b>X8247</b>	phillips flat m/s
<b>X8247B</b>	10/24 x 3/8 phillips pan head screw
<b>X8251</b>	phillips pan head m/s
<b>X8254</b>	shack proof lock washer

#### NOT ILLUSTRATED

<b>K1115</b>	expander, 1-1/2 x 1-1/4
<b>K1113G</b>	2" cuff
<b>X8150</b>	solution hose ties
<b>1503WD</b>	tmhd 1-1/2" x 25' blue hose w/ cuffs
<b>1504WDS</b>	tmhd 1-1/2" x 25' blue hose w/ solution hose & couplings
<b>1504WDE</b>	tmhd solution hose & cord assembly
<b>PX3A</b>	25' solution hose w/ couplings 100 psi @ 140° 3/8"
<b>PX28</b>	insulator boot for toggle switch
<b>SW141</b>	14/3 24' sjtw-a yellow cord
<b>PCT</b>	1" x 260" teflon tape